CHAPTER VII

EVALUATION OF THE IMPROVEMENT AFTER FMEA IMPLEMENTATION

7.1 Introduction

In this thesis, quality as shipped (QAS) and customer complaint as the indicators for demonstrating the improvement after FMEA implementation. The comparison of QAS between before and after implementation are shown from figure 7.1 to figure 7.35. In August, September and October 1997 are the three months of before implementation. And in April, May and June 1998 are the three months after implementation.

For the improvement on customer complaint items in manufacturing area is shown in figure 7.36 Basically, comparison of customer complaint items in manufacturing area is between before and after FMEA implementation. From April 1997 to October 1997 was the period of before FMEA implementation. From April 1998 to October 1998 was the period of after FMEA implementation.

7.2 Quality as shipped (QAS)

Currently, Molex Thailand use QAS and part per million concept to measure the quality of product before they are shipped to the end customers. For QAS, sampling plan is applied to gather defects of the product in each lot at the final gate which is before packing process, then comparison with the number of detection is considered. For the whole month, Molex Thailand gather all information for both number of defects and number of detection to make a part per million in each month.

For each lot, if it is more than acceptance level at the final gate, Molex Thailand will sort 100% of that batch and then summarize the quantity of defects and then divided by the total number of detection. Molex Thailand use this concept for each type of defect and show in the table and demonstrate as a graph for the whole month as well.

7.3 Comparison QAS between before and after FMEA implementation

In this thesis, QAS comparison before and after FMEA implementation are shown as the following. From Chapter III, there are five part number which are selected to implement FMEA technique and they will be evaluated by using QAS.

7.3.1 Part 889-4941 for wrong color wire be assembled

From figure 7.2 to figure 7.4 show all significant QAS of quality criteria in August, September and October 1997 respectively. This period is before FMEA implementation. From figure 7.5 to figure 7.7 show all significant QAS of quality criteria in April, May and June 1998 respectively which is the period of after FMEA implementation.

In figure 7.1 show the comparison between before and after FMEA implementation in wrong color wire be assembled quality criteria for part 889-4941. Before FMEA implementation, QAS of wrong color wire be assembled are 500 ppm, 533 ppm and 450 ppm in August, September and October 1997 respectively. After FMEA implementation in April, May and June 1998, QAS of wrong color wire be assembled quality criteria are all zero.

Comparision between before and after FMEA implementation in "Wrong colour wire be assembled" issue for P/N 889-4941




Figure 7.1- QAS comparison between before and after FMEA implementation for "wrong wire color be assembled" of Part number 889-4941

| | - Flamess | 20,000 | PPM | | | |
|---|--|---|--------------------------------|---|-----|---|
| 1. W | rong colour wire be assy | 10 | 500 | | | |
| 2. To | erminal bent | 8 | 300 | • | ** | |
| 3W | 'ire alternation | 4 | 200 | | | |
| | nlocked | 1 | 50 | | | |
| | TL is out of spec | 1 | 50 | | | |
| 6. O | thers | 3 | 4 6 6 1 | | i i | |
| | Criteria [| Defect (Q 2,480,000 1,158 | PPM 470 | | | |
| 4 1 | Criteria [| Defect (Q 2,480,000 | AP) | | | · |
| | Criteria [| Defect (Q 2,480,000 1,158 | AP) PPM 470 | | | |
| 2. W | Criteria [sul Over/Under C:Imp | Defect (Q 2,480,000 | AP) PPM 470 413 | \$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\ | | |
| 2. W | Criteria [sul Over/Under Citmp frong colour wire be assy fre alternation | Defect (Q 2,480,000 1,158 1,017 | PPM 470 413 246 183 | | | |
| 2. W 3. W 4. St 5. To | Criteria [sul Over/Under Crimp rong colour whe be assy ine alternation rip length is out of spec erminal bent | Defect (Q 2,480,000 1,158 1,017 604 451 418 | PPM 470 413 246 183 170 | | | |
| 2. W 3. W 4. St 5. T(8 E | Criteria C sul Over/Under Crimp rong colour wire be assy fire alternation rip length is out of spec erminal bent strude wire | Defect (Q 2,480,000 1,158 1,017 604 451 418 311 | PPM 470 413 246 183 170 126 | | | |
| 2. W 3. W 4. St 5. To 8 E | Criteria Camp rong colour wire be assy ire alternation rip length is out of spec eminal bent ktrude wire inch height is out of spec | Defect (Q 2,480,000 1,158 1,017 604 451 418 311 122 | PPM 470 413 246 183 170 126 50 | | | |
| 2. W 3. W 4. St 5. To 8. F 7. La | Criteria C sul Over/Under Crimp rong colour wire be assy fire alternation rip length is out of spec erminal bent strude wire | Defect (Q 2,480,000 1,158 1,017 604 451 418 311 | PPM 470 413 246 183 170 126 | | | |





Figure 7.2- QAS of all quality criteria in August 1997 for 889-4941







Figure 7.3- QAS of all quality criteria in September 1997 for 889-4941







Figure 7.4- QAS of all quality criteria in October 1997 for 889-4941






Figure 7.5- QAS of all quality criteria in April 1998 for 889-4941




Figure 7.6- QAS of all quality criteria in May 1998 for 889-4941

Insul Overfunder C Terrifiel best Lance height is out. Wire altered on Other Stein length is out. Editude wire. TTL is out of spac Wiring wire calour




Figure 7.7- QAS of all quality criteria in June 1998 for 889-4941

7.3.2 Part 889-4859 for wire alternation

From figure 7.9 to figure 7.11 show all significant QAS of quality criteria in August, September and October 1997 respectively. This period is before FMEA implementation. From figure 7.12 to figure 7.14 show all significant QAS of quality criteria in April, May and June 1998 respectively which is the period of after FMEA implementation.

In figure 7.8 show the comparison between before and after FMEA implementation in wire alternation quality criteria for part 889-4859. Before FMEA implementation, QAS of wire alternation are 625 ppm, 500 ppm and 500 ppm in August, September and October 1997 respectively. After FMEA implementation in April, May and June 1998, QAS of wire alternation quality criteria are 200 ppm, 200 ppm and 0 ppm respectively.

Comparision between before and after FMEAC mplementation in "Wire alternation" issue for P/N 889-4859





Figure 7.8- QAS comparison between before and after FMEA implementation for "wire alternation" of Part number 889-4859






Figure 7.9- QAS of all quality criteria in August 1997 for 889-4859





Figure 7.10- QAS of all quality criteria in September 1997 for 889-4859

meter Others Was is out of housing







Figure 7.11- QAS of all quality criteria in October 1997 for 889-4859







Figure 7.12- QAS of all quality criteria in April 1998 for 889-4859







Figure 7.13- QAS of all quality criteria in May 1998 for 889-4859






Figure 7.14- QAS of all quality criteria in June 1998 for 889-4859

7.3.3 Part 889-5034 for terminal bent

From figure 7.16 to figure 7.18 show all significant QAS of quality criteria in August, September and October 1997 respectively. This period is before FMEA implementation. From figure 7.19 to figure 7.21 show all significant QAS of quality criteria in April, May and June 1998 respectively which is the period of after FMEA implementation.

In figure 7.15 show the comparison between before and after FMEA implementation in terminal bent quality criteria for part 889-5034. Before FMEA implementation, QAS of terminal bent are 467 ppm, 800 ppm and 900 ppm in August, September and October 1997 respectively. After FMEA implementation in April, May and June 1998, QAS of terminal bent quality criteria are 83 ppm, 100 ppm and 100 ppm respectively.

Comparision between before and after FMEA implementation in "Terminal bent" issue for F/N 889-5034




Figure 7.15- QAS comparison between before and after FMEA implementation for "terminal bent" of Part number 889-5034

| 1. Terminal bent 2. Wrong colour wire be assy 3. Wire alternation 5. 167 4. Unlocked 5. TTL is out of spec 2. 67 6. Others Criteria Defect (QAF) 3,720,000 PFM 1. Insul OverUnder Crimp 1,459 3,720,000 PFM 2. Wire alternation 1,074 289 3. Wrong colour wire be assy 941 253 4. Terminal bent 5. Strip length is out of spec 5. Strip length is out of spec 6. Extuade wire 348 94 7. One side crimped 184 49 8. TTL is out spec 68 18 9. Others | 1. Terminal bent 14 487 2. Wrong colour wire be assy 8 267 3. Wire alternation 5 167 4. Unlocked 3 100 5. TTL is out of spec 2 67 6. Others 5 167 Criteria Defect (QAP) 3,720,000 PPM 1. Insul Over/Under Crimp 1,459 392 2. Wire alternation 1,074 269 3. Wrong colour wire be assy 941 253 4. Terminal bend 805 210 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One side crimped 184 49 6. TTL is out spec 68 18 | | | Hamess | Defect (C 30,000 | PPM | | | |
|--|---|----|------|-----------------------------|---------------------|------|----------|-----------------------|--|
| 2. Wrong colour wire be assy 8 267 3. Wire alternation 5 167 4. Unlocked 3 100 5. TTL is out of spec 2 67 6. Others 5 167 1. Insul Over/Under Crimp 1,459 392 2. Wire alternation 1,074 266 3. Wrong colour wire be assy 941 253 4. Terminal bend 805 216 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One side crimped 184 49 8. TTL is out spec 68 18 | 2. Wrong colour wire be assy 8 287 3. Wire alternation 5 167 4. Unlocked 3 100 5. TTL is out of spec 2 67 6. Others 5 167 Criteria Defect (QAP) 3,720,000 PPM 1. Insul Over/Under Crimp 1,459 392 2. Wire alternation 1,074 286 3. Wrong colour wire be assy 941 253 4. Terminal bend 805 210 5. Stip length is out of spec 500 134 6. Extrude wire 348 94 7. One side crimped 184 49 8. TTL is out spec 68 18 | | | Termina! bent | 14 | | | • | |
| 3. Wire alternation 5 167 4. Unlocked 3 100 5. TTL is out of spec 2 67 6. Others 5 167 Criteria Defect (QAF) 3,720,000 PPM 1. Insul OverUnder Crimp 1,459 392 2. Wire alternation 1,074 289 3. Wrong colour wire be assy 941 253 4. Terminal berd 805 218 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One side crimped 184 49 8. TTL is out spec 68 18 | 3. Wire alternation 5 167 4. Unlocked 3 100 5. TTL is out of spec 2 67 6. Others 5 167 Criteria Defect (QAP) 3,720,000 PPM 1. Insul Over/Under Crimp 1,459 392 2. Wire alternation 1,074 289 3. Wrong colour wire be assy 941 253 4. Terminal bent 805 210 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One side crimped 184 49 8. TTL is out spec 68 18 | | 2. | Wrong colour wire be assy | | | | | |
| 4. Unlocked 3 100 5. TTL is out of spec 2 67 6. Others 5 167 Criteria Defect (QAP) 3,720,000 PFM 1. Insul Over/Under Crimp 1,459 392 2. Wire alternation 1,074 289 3. Wrong colour wire be assy 941 253 4. Terminal berd 805 210 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One sido crimped 184 49 8. TTL is out spec 68 18 | 4. Unlocked 3 100 5. TTL is out of spec 2 67 6. Others 5 167 Criteria Defect (QAP) 3,720,000 PPM 1. Insul Over/Under Crimp 1,459 392 2. Wire alternation 1,074 289 3. Wrong colour wire be assy 941 253 4. Terminal berd 805 210 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One side crimped 184 49 8. TTL is out spec 68 18 | | 3. | Wire alternation | | | The Fall | | |
| 5. TTL is out of spec 2 67 6. Others 5 167 Criteria Defect (QAP) 3,720,000 PFM 1. Insul Over/Under Crimp 1,459 392 2. Wire alternation 1,074 289 3. Wrong colour wire be assy 941 253 4. Terminal bent 805 210 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One sido crimped 184 49 8. TTL is out spec 68 18 | Strip length is out of spec 2 67 | 4 | , | | | | | | |
| Criteria Defect (QAF) 3,720,000 PFM 1. Insul Over/Under Crimp 1,459 392 2. Wire alternation 1,074 289 3. Wrong colour wire be assy 941 253 4. Terminal berd 805 218 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One sido crimced 184 49 8. TTL is out spec 68 18 | Criteria Defect (QAF) 3,720,000 PPM 1. Insul OverUnder Crimp 1,459 392 2. Wire alternation 1,074 288 3. Wrong colour wire be assy 941 253 4. Terminal berd 805 218 5. Strip length is out of spec 500 134 6. Extude wire 348 94 7. One sido crimped 184 49 8. TTL is out spec 68 18 | 7 | 5. | | | | 1 " | | |
| 3,720,000 PFM 302 | 3,720,000 PFM 1. Insul OverUnder Crimp 1,459 392 2. Wire alternation 1,074 269 3. Wrong colour wire be assy 941 253 4. Terminal ber4 805 218 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One side crimped 184 49 8. TTL is out spec 68 18 | | 6. | Others | 5 | 167 | | | |
| 3,720,000 PFM 1. Insul OverUnder Crimp 1,459 392 2. Wire alternation 1,074 269 3. Wrong colour wire be assy 941 253 4. Terminal ber4 805 218 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One side crimped 184 49 8. TTL is out spec 68 18 | 3,720,000 PFM 1. Insul Over/Under Crimp 1,459 392 2. Wire alternation 1,074 289 3. Wrong colour wire be assy 941 253 4. Terminal berk 805 210 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One side crimped 184 49 8. TTL is out spec 68 18 | | | O-ita-i- | Defect /C | AEA. | | | |
| 1. Insul Over/Under Crimp 1,459 392 2. Wire alternation 1,074 269 3. Wrong colour wire be assy 941 253 4. Terminal bent 805 218 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One side crimped 184 49 8. TTL is out spec 68 18 | 1. insul Over/Under Crimp 1,459 392 2. Wire alternation 1,074 289 3. Wrong colour wire be assy 941 253 4. Terminal bent 805 218 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One side crimped 184 49 8. TTL is out spec 68 18 | | | Cntena | | PPM | 177 | , | |
| 3. Wrong colour wire be assy 941 253 4. Terminal bent 805 216 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One sido crimced 184 49 8. TTL is out spec 68 18 | 3. Wrong colour wire be assy 941 253 4. Terminal bent 805 210 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One sido crimced 184 49 8. TTL is out spec 68 18 | | 1. | Insul Over/Under Crimo | | 392 | 5.0 | | |
| 3. Wrong colour wine be assy 941 253 4. Terminal bent 805 216 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One sido crimced 184 49 8. TTL is out spec 68 18 | 3. Wrong colour wine be assy 941 253 4. Terminal bent 805 210 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One sido crimced 184 49 8. TTL is out spec 68 18 | | 2. | Wire alternation | 1,074 | 289 | | | |
| 4. Terminal bent 805 216 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One sido crimced 184 49 8. TTL is out spec 68 18 | 4. Terminal bent 805 216 5. Strip length is out of spec 500 134 6. Extrude wire 348 94 7. One side orimized 184 49 8. TTL is out spec 68 18 | -, | 3. | Wrong colour wire be assy | 941 | 253 | 19.7% | | |
| 6. Extrude wire 348 94 7. One side crimced 184 49 8. TTL is out spec 68 18 | 6. Extrude wire 348 94 7. One side crimced 184 49 8. TTL is out spec 68 18 | | 4. | Terminal bent | | | 4.00 | | |
| 6. Extrade wire 348 94 7. One side crimced 184 49 8. TTL is out spec 68 18 | 6. Extrade wire 348 94 7. One sido crimced 184 49 8. TTL is out spec 68 18 | | 5. | Strip length is out of spec | | | | | |
| 8. TTL is out spec 68 18 | 8. TTL is out spec 68 18 | • | | Extrude wire | | 94 | | And the second second | |
| | | • | ; O. | | 184 | 49 | | | |
| 9. Otners 147 40 | 9. Otners 147 40 | • | | One side crimced | | | | | |
| | | | 7. | TTL is out spec | 68 | | | | |




Figure 7.16- QAS of all quality criteria in August 1997 for 889-5034

| r | | Hames | a Defect (0 | PPM | ** | | • | |
|----------|-----------------------------------|----------------------|--------------------|-------------------|-----------------|--|----|---|
| · • | 1 Termi | nal bent | 16 | 800 | | | | |
| † | | colour wire be ass | | 300 | | | | |
| | 3. Wire | sitemation | | 300 | | | | |
| 13 | 4. Unloc | ked | - 5 | 250 | | | | |
| | | out of spec | 4 10 10 10 1 | 50 150 | | | | |
| - 1 | 6. Other | t service | 3 | 150 | | 11,7 | | |
| | | | | | | *** | | |
| | | | | | | *. | | |
| | | Criter | a Defect (0 | DAP) | | | | |
| * | | Cition | | | | | | |
| | d deput | Over/Under Crimp | 2,48C,000 1,022 | 442 | | 2 | | |
| 1 × 1 | 7. Missil | alternation | 800 | 323 | s in the second | ta est de la capital de la | | |
| | 2. VVIIE | nal bent | 621 | 412 323 250 | | | | |
| | 4 Strin | ength is out of spec | | 204 | | 54 - 125 - E | | |
| | 5 Wood | colour wire be ass | v 307 | 124 | | 1011 | • | |
| | | 6 wire | 243 | 98 | | | ** | |
| 100 | | | | 98 52 | | erini Egeleni | | |
| | 7. iOne s | ide crimped | 120 | | | | | |
| | 7. iOne s 8. TTL is | ide crimped | 128 | 19 | | | | |
| | 7. One s 8. TTL is 9. Other | out spec | | 19 | | •. • | | |
| | 8. TTL is | out spec | 46 | 19 | | | | |
| | 8. TTL is | out spec | 46 | 19 | | | | ٠ |
| | 8. TTL is | out spec | 46 | 19 | | | | |




Figure 7.17- QAS of all quality criteria in September 1997 for 889-5034





Figure 7.18- QAS of all quality criteria in October 1997 for 889-5034

Insti Overlander C. Terminal bert. Wiong cold Water adversarion. Since langth is ext.







Figure 7.19- QAS of all quality criteria in April 1998 for 889-5034







Figure 7.20- QAS of all quality criteria in May 1998 for 889-5034






Figure 7.21- QAS of all quality criteria in June 1998 for 889-5034

7.3.4 Part 889-0692 for wire is out off housing

From figure 7.23 to figure 7.25 show all significant QAS of quality criteria in August, September and October 1997 respectively. This period is before FMEA implementation. From figure 7.26 to figure 7.28 show all significant QAS of quality criteria in April, May and June 1998 respectively which is the period of after FMEA implementation.

In figure 7.22 show the comparison between before and after FMEA implementation in wire is out off housing quality criteria for part 889-0692. Before FMEA implementation, QAS of wrong color wire be assembled are 600 ppm, 500 ppm and 500 ppm in August, September and October 1997 respectively. After FMEA implementation in April, May and June 1998, QAS of wire is out off housing quality criteria are all zero.

Comparision betwee.. before and after FMEA implementation in "Wire is out of housing" issue for P/N 889-0692




Figure 7.22- QAS comparison between before and after FMEA implementation for "wire is out off housing" of Part number 889-0692

| • | | | | | | , |
|---|---------------------------------|--|--|----|--|---|
| | 1314 | Criteria | Defect (QAS) | e. | t grant to | |
| | - | Harness | 25,000 PPM | | | |
| | _1. | Wire is out of housing | 14 580 | | | |
| | 2. | Terminal bent | 6 240 | | | |
| | 3. | Alternation housing | 6 200 | | | |
| | 4. | Unlocked | 3 120 | | | |
| | 5. | Tube is out of spec | 1 40 | | | |
| | 6. | Others | 4 160 | | | |
| | | Criteria | 4 300 000 | | and the second second | |
| | | era est | 1 700 000 PPM | | the State of the S | |
| | 1. | | 1,700,000 PPM | | | |
| | 1. 2 | Insul Over/Under Crimp One side crimped | 1,700,000 PPM 2,100 1,235 438 258 | | | |
| | 1. 2. 3. | Insul Over/Under Crimp One side crimped Alternation housing | 1,700,000 PPM 2,100 1,235 | | | |
| | 1. 2 3. 4. | Insul Over/Under Crimp One side crimped Alternation housing Terminal bent | 1,700,000 PPM 2,100 1,235 438 258 422 248 390 229 | | | · |
| | 1. 2. 3. 4. 5. | Insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec | 1,700,000 PPM 2,100 1,235 438 258 422 248 390 229 155 91 | | | |
| | 1. 2 3. 4. 5. 6. | Insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing | 1,700,000 PPM 2,100 1,235 438 258 422 248 390 229 155 01 131 77 | | | |
| | 6. | Insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec | 1,700,000 PPM 2,100 1,235 438 256 422 248 390 229 155 91 131 77 24 14 | | | |
| | 6. 7. 8. | Insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec TTL is out spec | 1,700,000 PPM 2,100 1,235 438 256 422 248 390 229 155 01 131 77 24 14 | | | |
| | 6. 7. 8. | Insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec | 1,700,000 PPM 2,100 1,235 438 256 422 248 390 229 155 91 131 77 24 14 | | | |
| | 6. 7. 8. | Insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec TTL is out spec | 1,700,000 PPM 2,100 1,235 438 256 422 248 390 229 155 01 131 77 24 14 | | | |
| | 6. 7. 8. | Insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec TTL is out spec | 1,700,000 PPM 2,100 1,235 438 256 422 248 390 229 155 01 131 77 24 14 | | | |
| | 6. 7. 8. | Insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec TTL is out spec | 1,700,000 PPM 2,100 1,235 438 256 422 248 390 229 155 01 131 77 24 14 | | | |
| | 6. 7. 8. | Insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec TTL is out spec | 1,700,000 PPM 2,100 1,235 438 256 422 248 390 229 155 01 131 77 24 14 | | | |




Figure 7.23- QAS of all quality criteria in August 1997 for 889-0692

| | | | Defect (C | AS) | | | ey Million | | |
|-------|----------------------------------|--|--|---|-------|---------|------------|------|-----|
| | | Hamess | 15,000 | PPM | | ' | | | |
| | 1. | Wire is out of housing | 8 | 200 | | | | | |
| | 2. | Terminal bent | 3 | | | | 4.5 | | |
| 200 | 3. | Alternation housing | 2 | 133 67 | أعليا | 1 447 S | | | |
| | 4. | Unlocked | | 67 | | | | | |
| i ili | 5. | Tube is out of spec | | 133 | .1. | 5.52 | | | |
| | 6. | Others | 2 | 133 | | . 51 | · . | | 1.5 |
| | | Cntena | Defect (C | | | | | | |
| | 1. | Insul Over/Under Crimp | 1,020,000 1,015 | PPM 995 | | | | | |
| | 2. | Insul Over/Under Crimp One side crimped | 1,020,000 1,015 327 | 995 321 | | | | | |
| | 2. 3. | Insul Over/Under Crimp One side crimped Alternation housing | 1,020,000 1,015 327 288 | 995 321 280 | | | | | |
| | 2. 3. 4. | insul Over/Under Crimp One side crimped Alternation housing Terminal bent | 1,020,000 1,015 327 288 250 | 995 321 280 245 | | | | | |
| | 2. 3. 4. 5. | insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lence height is out of spec | 1,020,000 1,015 327 286 250 132 | 995 321 280 245 | | | | | |
| | 2. 3. 4. 5. 6. | insul Over/Under Crimp One side crimped Alternation housing Treminal bent Lance height is out of spec Strip length is out of housing | 1,020,000 1,015 327 286 250 132 60 | 995 321 280 245 | | | | | |
| | 2. 3. 4. 5. 6. 7. | insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec | 1,020,000 1,015 327 288 250 132 60 | 995 321 280 245 129 59 | | | | | |
| | 2. 3. 4. 5. 6. 7. | insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec TTL is out spec | 1,020,000 1,015 327 286 250 132 60 16 | 995 321 280 245 129 59 16 | | | | | · · |
| | 2. 3. 4. 5. 6. 7. | insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec | 1,020,000 1,015 327 288 250 132 60 | 995 321 280 245 129 59 | | | | | |
| | 2. 3. 4. 5. 6. 7. | insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec TTL is out spec | 1,020,000 1,015 327 286 250 132 60 16 | 995 321 280 245 129 59 16 | | | | | |
| | 2. 3. 4. 5. 6. 7. | insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec TTL is out spec | 1,020,000 1,015 327 286 250 132 60 16 | 995 321 280 245 129 59 16 | | | | | |
| | 2. 3. 4. 5. 6. 7. | insul Over/Under Crimp One side crimped Alternation housing Terminal bent Lance height is out of spec Strip length is out of housing Tube is out of spec TTL is out spec | 1,020,000 1,015 327 286 250 132 60 16 | 995 321 280 245 129 59 16 | | | | | |




Figure 7.24- QAS of all quality criteria in September 1997 for 889-0692

| | Criteria | Defect (Q/ | 4S) 🕝 |
|-----|------------------------|------------|-------|
| ı—— | Hamess | 10,000 | PPM |
| 1 | Wire is out of housing | 5 | 500 |
| 2. | Terminal bent | 2 | 200 |
| 3. | Alternation housing | 2 | 200 |
| 4. | Unlocked | | 100 |
| 5. | Tube is out of spec | 1 1 1 | 100 |
| 6. | Others | 1 | 100 |

| | Criteria C | | | |
|----|--------------------------------|---------|-------|--|
| | | 680,000 | PPM | |
| 1. | Insui Over/Under Crimp | 687 | 1,010 | |
| 2. | One side crimped | 260 | 382 | |
| 3. | Terminal bent | 251 | 369 | |
| 4. | Alternation housing | 126 | 185 | |
| 5. | Lance height is out of spec | 90 | 132 | |
| 6. | Strip length is out of housing | 35 | 51 | |
| 7. | Tube is out of spec | 21 | 31 | |
| 8. | TTL is out spec | 13 | 19 | |
| 8. | Others | 34 | 50 | |





Figure 7.25- QAS of all quality criteria in October 1997 for 889-0692

| Criteria | Defect | (OAS) |
|----------|--------|--------|
| VALUE HA | Delect | I WAD. |

| | Hamess | 7 | 7,000 | PPM |
|----|--|----------|-------|-----------------|
| 1 | Terminal bent | | 1 | 143 |
| 2. | Alternation housing | | 1 | 143 |
| 3. | Unlocked | To pick. | - 1 | 143 |
| 4. | Tube is out of spec | | . 1 | 143 |
| 5. | 1 A A A A A A A A A A A A A A A A A A A | 46.10 | | er javrinstes Q |
| Ä | | 7.7 | | 0 |

Criteria Defect (QAP)

| | | 476, | 000 | PPM_ |
|---------------|-----------------------------|-------------|-----|------|
| ٦. | Terminal bent | 10 to 10 to | 194 | 408 |
| 2. | One side crimped | | 176 | 370 |
| 3. | Lance height is out of spec | Carrer - | 78 | 164 |
| 4. | Alternation housing | 14. | 65 | 137 |
| 5. | Strip length is out of spec | grafinos" | 42 | 88 |
| - <u>5</u> : | Insul Over/Under Crimp | | 40 | 84 |
| - | Tube is out of spec | | 13 | 27 |
| 8. | TTL is out spec | 1 14 | 10 | 21 |
| 9. | Others | 7.77 | 54 | 113 |






Figure 7.26 QAS of all quality criteria in April 1998 for 889-0692

| | . (| Criteria I | Defect ((| QAS) - |
|----|---------------------|------------|--------------|--------|
| | | Hamess | 7,000 | PPM |
| 1. | Alternation housing | | 1 | 143 |
| 2. | Terminal bent | 100 | 1 | 143 |
| 3. | Unlocked | vag re | - 1 | 143 |
| 4. | | 1.7 | . 1 53 | 0 |
| 5. | F STREET | 1.40 | err ligger | - 0 |
| 6. | | 1120 1 1 2 | Karolina e 🔪 | 0 |

| | Criteria | Jetect (Q | |
|----|-----------------------------|-----------|----------|
| | | 476,000 | PPM |
| 1. | Terminal bent | 205 | 431 |
| 2. | One side crimped | 157 | 330 |
| 3. | Lance height is out of spec | 99 | 208 |
| 4. | Alternation housing | 62 | 130 |
| 5. | Strip length is out of spec | 44 | 92 |
| ô. | Insul Over/Under Crimp | 40 | 84 |
| 7. | Tube is out of spec | 30 | 84 63 |
| 8. | TTL is out spec | 20 | 42 |
| 9. | Others | 30 | 63 |




Figure 7.27- QAS of all quality criteria in May 1998 for 889-0692

| | (| Criteria D | efect (C | ≀AS) |
|----|---------------------|------------|----------|------|
| | | Hamess | 10,000 | PPM |
| 1. | Alternation housing | g | 2 | 200 |
| 2. | Terminal bent | i i | 2 | 200 |
| 3. | Tube is out of spe | С | 24cm 1 | 100 |
| 4. | Unlocked | | 1 | 100 |
| 5. | | | | _ 0 |
| 6. | | | | 0 |

| | Criteria Defect (QAP) | | | |
|----|-----------------------------|---------|-----------------------------|--|
| | * (| 680,000 | PPM | |
| 1. | Terminal bent | 298 | 438 | |
| 2. | One side crimped | 234 | 344 | |
| 3. | Lance height is out of spec | 155 | 228 | |
| 4. | Alternation housing | 120 | 176 | |
| 5. | Strip length is out of spec | 70 | 103 | |
| 6. | Insul Over/Under Crimp | 67 | 99 | |
| 7. | Tube is out of spec | 16 | 24 | |
| 8. | TTL is out spec | 15) | 103 99 24 22 49 | |
| 9. | Others | 33 | 49 | |




Figure 7.28- QAS of all quality criteria in June 1998 for 889-0692

7.3.5 Part 889-4529 for unlocked

From figure 7.30 to figure 7.32 show all significant QAS of quality criteria in August, September and October 1997 respectively. This period is before FMEA implementation. From figure 7.33 to figure 7.35 show all significant QAS of quality criteria in April, May and June 1998 respectively which is the period of after FMEA implementation.

In figure 7.29 show the comparison between before and after FMEA implementation for unlocked quality criteria for part 889-4529. Before FMEA implementation, QAS of unlocked are 600 ppm, 500 ppm and 500 ppm in August, September and October 1997 respectively. After FMEA implementation in April, May and June 1998, QAS of unlocked quality criteria are all zero.

Comparision between before and after FMEA implementation in "Unlocked" issue for P/N 889-4529





Figure 7.29- QAS comparison between before and after FMEA implementation for "unlocked" of Part number 889-4529






Figure 7.30- QAS of all quality criteria in August 1997 for 889-4529

| Harnes | 10,000 PPM | | | | |
|--------------------------------|--------------|------------------------|--|--|---|
| | 500 | | | | |
| 1. Unlocked | 3 300 | f | | | |
| | 1 100 | | -1:-211 | | |
| 3. Will is out of flouring | 100 | | | | |
| | 1 12 | | | | |
| 5. Others | | | | | III a die ee |
| 5. | 3 | | | | |
| | | | 1111 | | |
| | | | ., | | |
| Criteria | Defect (OAP) | | | | |
| | | | | | jen ar inde |
| | 400 PFM | | | | |
| T. Insul Overrunder Chmp | 400 60 | | | | |
| 2. Terminal bent | 344 | | | | |
| 3. Alternation housing | 125 200 | | | | |
| 4. Extrude wire | 117 19 | | | | |
| 5. Strip length is out of spec | 84 140 | | | | |
| 6. Lance height is out of spec | 51 89 | | | | |
| 7. Tube is out of spec | 161 27 | | | | |
| | | | | | |
| 9 Others | 24. | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | Wire is out of housing | Wire is out of housing 1 100 Alternation housing 1 100 Others 1 100 Others 1 100 O 0 Criteria Defect (QAP) Section Section Section Section | Wire is out of housing 1 100 Alternation housing 1 100 Others 1 100 Others 1 100 O 0 0 Criteria Defect (QAP) Second PPM Insul OverfUnder Crimp 400 667 Terminal bent 344 573 Alternation housing 125 208 Estrude wire 117 164 Strip length is out of spec 54 140 Lance height is out of spec 51 85 Tube is out of spec 16 27 TTube is out of spec 16 27 TTube is out of spec 5 5 | Wire is out of housing 1 100 Alternation housing 1 100 Others 1 100 Others 1 100 O 0 0 Criteria Defect (QAP) 600,000 PPM 1 Insul OverrUnder Crimp 400 667 2 Terminal bent 344 573 3 Alternation housing 125 208 4 Extrude wire 117 195 5 Strip length is out of spec 84 140 5 Strip length is out of spec 51 85 7 Tube is out of spec 51 85 7 Tube is out of spec 3 5 |





Figure 7.31- QAS of all quality criteria in September 1997 for 889-4529






Figure 7.32- QAS of all quality criteria in October 1997 for 889-4529





Figure 7.33- QAS of all quality criteria in April 1998 for 889-4529







Figure 7.34- QAS of all quality criteria in May 1998 for 889-4529






Figure 7.35- QAS of all quality criteria in June 1998 for 889-4529

7.4 Comparison customer complaint items in manufacturing area between before and after FMEA implementation

In this thesis, comparison between before and after FMEA implementation of customer complaint items in manufacturing is shown in figure 7.36. In this figure 7.36 show the customer complaint items in manufacturing area in 1997 and 1998.

In table 7.1 show the number of customer complaint items in manufacturing area in April, May, June, July, August, September and October 1997 against 1998 by monthly. In 1997 is the period of before FMEA implementation and in 1998 is the period of after FMEA implementation

Table 7.1- Customer complaint items in manufacturing area in 1997 against 1998

| Monthly customer complaint items in n | In 1997 | In 1998 | | |
|---------------------------------------|---------|---------------------------------|------|--|
| April | | 6.0 | 4.0 | |
| May | | 5.0 | 3.0 | |
| June | | 3.0 | 2.0 | |
| July | | 4.0 | 3.0 | |
| August | | 5.0 | 2.0 | |
| September | | 5.0 | 2.0 | |
| October | | 4.0 | 2.0 | |
| | Total | 32.0 | 18.0 | |
| | Average | 4.57 | 2.57 | |
| | | Percentage improvement is 43.76 | | |

Source: The figure of customer complaint items in manufacturing in 1997 and 1998 are shown in Appendix E

Improvement on Customer complaints after FMEA implementation




Figure 7.36- Comparison of customer complaint items in manufacturing area between before and after FMEA implementation

7.5 Standard procedure for product quality improvement

After FMEA implementation, FMEA team come out the standard procedure which have been described in seven cases as following

Case I: Standard procedure for setting up crimping machine
This standard procedure help to reduce the following quality criteria

- 1 Terminal bent
- 2. Wire is out off housing
- 3. Unlocked

Case II: Standard procedure for preventive maintenance level II and level III This standard procedure help to reduce "Unlocked"

Case III: Standard procedure for crimping specification and tolerance analysis This standard procedure help to reduce "Wire is out off housing"

Case IV: Standard procedure for tighten sampling plan and reduced sampling plan This standard procedure help to reduce the following quality criteria

- 1. Wrong wire color be assembled
- 2. Terminal bent
- 3. Unlocked

Case V: Standard procedure for continuity test
This standard procedure help to reduce "Wire alternation"

Case VI: Standard procedure for color checker

This standard procedure help to reduce "Wrong wire color be assembled"

Case VII: Standard new carton
This standard procedure help to reduce "Terminal bent"

Case I: Standard procedure for setting up crimping machine
This standard can be applied to crimping process which is described as following.

- 1 Assembly the applicator on the bolster plate and lock by screws
- 2 Put the terminal to guide feed of applicator and lock it
- 3 Turn on power supply 220V and ensure pilot lamp is light
- 4 Start electric motor at output 300W and rotate fly wheel in the direction given by V-belt.
 - 5 Push foot switch one time.
 - 6 Check the punch, terminal and anvil are aligned
 - 7 Insert wire and crimp terminal
- 8 Check with Molex specification. If the crimping is out off specification, turn the locked nut.
- 9 Adjust the crimping height by turning adjust dial with adjust handle 0.03 mm per scale. If crimping height is too low, adjust to the left. If crimping height is too height, adjust to the right
- 10 When crimping is under specification, lock the nut softly and fix screw at position "A" and "B" strongly
 - 11 Then fix the locked nut strongly again

Case II: Standard procedure for peventive maintenance of level II and level III

FMEA team review level II and level III of preventive maintenance and come out the
criteria which needed to be checked and inspected. Those criteria for both level II and level III of
preventive maintenance are shown as following

1 Level II of preventive maintenance

There are five main things that must be checked for level II of preventive maintenance and they are listed out as following

- 1.1 Swivel arms and Grippes
 There are ten things that needed to be inspected
- 1 Swivel cylinder
- 2 Bush holder

- 3 Swivel bush
- 4 Shock absorber
- 5 Rod eyes
- 6 Tie bar bush
- 7 Grooved ball bearings
- 8 Gripper finger
- 9 Lever
- 10 Tension of tooth belt
- 1.2 Measuring unit and cutter block
 There are five things that needed to be checked
- 1 Knock out blades
- 2 Center cutter
- 3 Strippers
- 4 Measuring roller
- 5 Check proper function of piece counter
- 1.3 Pneumatic unit
 There are four things that needed to be checked
- 1 Air regulator at 6 bar
- 2 Lubricator unit (oil level) 1 drop/5min
- 3 Pressure limit switch
- 4 Air filter
- 1.4 Electric parts
- 1 Clean magnetic contactor
- 2 Clean filter
- 3 Clean relay
- 4 Check all sensor
- 1.5 Others
- 1 Clean the entire machine
- 2 Lubricate all moving part

2 Level III of preventive maintenance

There are five main things that must be checked for level III of preventive maintenance and they are listed out as following

2.1 Swivel arms and grippers

There are eleven things that needed to be checked

- 1 Dismantle and clean the swivel arms and gripper
- 2 Check bush holder
- 3 Swivel bush
- 4 Shock absorber
- 5 Rod eyes
- 6 Tie bar bush
- 7 Swivel cylinder
- 8 Grooved ball bearings
- 9 Gripper finger
- 10 Lever
- 11 Tension of tooth belt

1.2 Measuring unit and cutter block

There are seven things that needed to be checked

- 1 Knock out blades
- 2 Center cutter
- 3 Strippers
- 4 Measuring roller
- 5 Check proper function of piece counter
- 5 Dismantle and clean the cutter block
- 7 Dismantle and clean measuring unit

1.3 Pneumatic unit

There are four things that needed to be checked

- 1 Air regulator at 6 bar
- 2 Lubricator unit (oil level) 1 drop/5min
- 3 Pressure limit switch
- 4 All control values

1.4 Electric parts

There are six things that needed to be checked

- 1 Clean magnetic contactor
- 2 Clean filter
- 3 Clean relay
- 4 Check all sensor
- 5 Check carbon bush of the drive motor
- 6 Clean drive motor
- 1.5 Others
- 1 Clean the entire machine
- 2 Lubricate all moving part

Case III: Standard procedure for crimping specification and tolerance analysis

This analysis can be a guideline to determine new crimping specification of any new
terminal of harness wire assembly. Result of this analysis can be able to modify crimping
specification when quality problem has been occurred. This analysis is to enhance determination
of customer specification.

1 Crimp specification

There are two parts that needed to be analyzed for crimping specification. Firstly, it is the strip length and secondly, it is crimp height. Figure 7.37 show the picture of stripped wire and crimped wire.




Figure 7.37- Stripped wire and crimped wire

- 1.1 Strip length for crimping terminal In figure 7.37 show the picture of stripped wire.
- 1.1.1 Criteria that needed to be considered
- 1 Extrude wire from conductor barrel
- 2 Position of insulation end between conductor barrel and insulator barrel
- 1.1.2 Define the nominal strip length which considered from insulation end point. This end point should be located in the middle between conductor and insulator barrel. And the end of extrude wire should be in the middle between conductor barrel and end of mating zone. In figure 7.38 shows the position of insulation end and the position of extrude wire. In this figure 7.38 show the improperly crimped wire
 - 1.1.3 Define the strip length's tolerance. Consideration of the range between conductor and insulator barrel is a must.
- 1.1.4 Cut and strip the wire according to the dimension and tolerance which was set in step 1.1.3 and 1.1.4 by using the upper limit number and lower limit number and then verify the strip length by practical crimping with wire so as to be able to adjust the tolerance again.




Figure 7.38- Example of improperly crimped wire

1.2 Crimp height

There are two type of improperly crimped wire.

1.2.1 Conductor crimped height

- 1 To evaluate the conductor crimp height, it is needed to refer to crimp strength of the terminal which has the same specification. For board-in terminal, it is needed to consider PCB hole as well because PCB hole is a part to limit the crimp height.
- 2 Prepare strip wire and then crimp the wire with different crimp height to test the crimp strength. Result of that the upper and lower specification of crimping specification can be identified.
- 3 After getting the middle value of crimp height, do insert into housing or print circuit assembly board (PCB) to test quality criteria.

1.2.2 Insulator crimped height

1 To evaluate insulator crimp height, type of wire and its application are the major thing to be considered. For example, UL 1015 has double insulator. UL 1617 is thicker than UL 1007. See figure 7.39. The thickness of insulator will limit the tolerance of insulator crimp height. In figure 7.39 show the cross section of wire and show the good crimped wire and bad crimped wire.




Figure 7.39- Insulator barrel cross section

2 To verify defined insulator crimp height specification, do adjust the tooling by using sample of crimped wire as an signal to adjust. Figure 7.40 show the maximum insulator crimp height and minimum insulator crimp height.




Figure 7.40- Insulator barrel cross section

- 3 After define insulator crimp height specification, do insert into housing or PCB to conform final specification or customer specification.
 - 1.3 Analysis wire length's tolerance There are two parts to be considered
- 1.3.1 Check the capability of cutting machine whether to be able to meet customer required specification or not
- 1.3.2 Consider the tolerance of the customer requirement specification and split the assembled part into components and add the tolerance of all components which has the same direction as follow
 - 1 Crimping position tolerance
 - 2 Strip length tolerance
 - 3 Cut wire tolerance

When measure the wire length after insertion into housing, the wire need to be pulled a bit to get the lance hit the locking lance in the housing, so this tolerance will not be considered.

Case IV: Standard procedure for tighten sampling plan and reduced sampling plan Samples must be taken randomly from the submitted lot according to the C=0 sampling plans with switching rule. Whenever the sampling plan was done and found only one reject part, Molex Thailand will reject the whole lot and Molex Thailand will sort the whole lot in house before that lot be shipped to customer.

1 The starting inspection point for any part number is normal level at AQL = 0.1 with C=0. See table 5.1 for sampling plan with C=0

- 2 Condition for normal level (AQL = 0.40 with C=0) to reduced level (AQL = 0.10 with C=0) This will be effective when the bellowing condition is exist.
 - 2.1 Five consecutive lots are accepted
 - 3 Condition for reduced level (AQL = 0.4 with C=0) to normal level (AQL = 0.1 with C=0) This will be effective when any one of the bellowing condition is exist.
 - 3.1 Any lot was rejected
 - 3.2 Irregular production

For example, there is no production in the last 10 consecutive working days

- 3.3 After ten lots was inspected
- 4 Condition for normal level (AQL = 0.1 with C=0) to tightened level (AQL = 0.04 with C=0) This will be effective when the bellowing condition is exist
 - 4.1 Two of five consecutive lots was rejected
 - 5 Condition for tightened level (AQL = 0.01 with C=0) to Normal level (AQL = 0.1 with C=0) This will be effective when the bellowing condition is exist
 - 5.1 Five consecutive lots accepted

Case V: Standard procedure for continuity test

- 1 Choose the suitable continuity tester for the harness which will be tested
- 2 Connect the chosen continuity tester to power supply and check its function. This is to make sure that it is functional

- 3 Connect one end of harness with the mating connector and do the same thing with another end of harness
- 4 If the signal is active, that harness wire is accepted. But if the signal is not active, that harness will be rejected that needed to be reworked

Case VI: Standard procedure for color cable checker

- i Turn on color cable checker
- 2 Wait five minutes
- 3 Set number of wire to be checked
- 4 Press reset bottom
- 5 Press clear bottom to clear memory
- 6 Slide wire to the guide
- 7 Check the result with table 7.2
- 8 If the reject was found, it will has sound. Press reset bottom to stop that sound
- 9 When checking is completed as much as assigned, there will be Beep Beep sound

Table 7.2- Result of checking

| Result | Light signal | Sound | Counter |
|---|--------------|------------------------------------|-------------|
| accept | Green | Beep sound three times | auto count |
| reject color orientation | Red | Continue Beep sound high frequency | press reset |
| reject no of wire | Red | Continue Boo sound low frequency | press reset |
| Speed error for both good and defect part | Yellow | Continue Boo sound | press reset |

Case VII: Standard new carton

Molex Thailand change the thickness of carton from three layers to five layers which are shown in figure 7.41 and 7.42 respectively




Figure 7.41- 3 layers carton




Figure 7.42-5 layers carton

สถาบนวิทยบริการ จฬาลงกรณ์มหาวิทยาลัย